

Message

---

**From:** Mickunas, Dave [Mickunas.Dave@epa.gov]  
**Sent:** 10/1/2018 5:34:46 PM  
**To:** Powell, Greg [Powell.Greg@epa.gov]  
**CC:** Moore, Gary [Moore.Gary@epa.gov]; Singhvi, Raj [Singhvi.Raj@epa.gov]; Blaze, Stephen [Blaze.Stephen@epa.gov]  
**Subject:** Re: F.J. Doyle Salvage Stie

To do due diligence, I think that you would want to analyze for dioxin.

Sent from my iPhone

On Oct 1, 2018, at 9:08 AM, Powell, Greg <[Powell.Greg@epa.gov](mailto:Powell.Greg@epa.gov)> wrote:

If you look for them you will probably find some of the isomers of dioxin. I'll forward to our chemists.  
Steve ,Dave and Raj any input?

Greg Powell  
USEPA-ERT  
Erlanger, KY Office  
(859)594-6549 office  
(513)607-1572 cell

"Facts do not cease to exist because they are ignored."

---

**From:** Moore, Gary  
**Sent:** Monday, October 01, 2018 11:47 AM  
**To:** Powell, Greg <[Powell.Greg@epa.gov](mailto:Powell.Greg@epa.gov)>  
**Subject:** F.J. Doyle Salvage Stie

Greg:

Can you get this to the right person if not you?

We are going to be demolishing a building at a former PCB dismantling facility. They did do cutting and grinding on the transformers. It is a metal building with wood structures.

We are going to do the following: Asbestos Inspection – Required for Reno/Demo  
We are planning on doing PCB wipe samples to include analysis for Aroclor 1268 (Galbestos?)  
We are going to sample for lead paint

Question: Is there a need to include Dioxins/Furans for the wipe samples?

Thanks

**Gary W. Moore (6SF-ER)**  
**Federal On-Scene Coordinator**  
**U.S EPA Region 6**  
**1445 Ross Ave, Suite 1200**  
**Dallas, TX 75202-2733**  
**Cell: 214.789.1627**  
[moore.gary@epa.gov](mailto:moore.gary@epa.gov)